

Attachment #1

Onsite Wastewater Mngt Services, Inc.
P.O. Box 51
Ostrander, Ohio 43061

Invoice

| Date | Invoice # |
|-----------|-----------|
| 6/20/2019 | 25789 |

| |
|--|
| Bill To |
| Ed Williams 1946 Ford Rd. Delaware, Ohio 43015 |

| |
|---------------------------|
| E-mail & Phone |
| cdkstructures@aol.com |
| cell: 614.206.4627 |

| |
|--------------|
| Terms |
| Net 30 |

| Description | Rate | Quantity | Amount |
|--------------------|--------|----------|--------|
| 6 month inspection | 250.00 | | 250.00 |
| Filter | 0.00 | | 0.00 |
| Sales Tax | 6.75% | | 0.00 |

| | | |
|---|-------------------------|----------|
| | Total | \$250.00 |
| Any amount unpaid after thirty (30) days from the date of this invoice shall accrue interest at a rate of three (3%) percent per month. | Payments/Credits | \$0.00 |
| | Balance Due | \$250.00 |

Attachment 1

ONSITE WASTEWATER MANAGEMENT SERVICES, INC.

Cell : 614-206-4627 Office: 740-666-1334

INSPECTION/SERVICE REPORT

Date: 6/19/2019 Service Technician: Shawn

Billable

Warrantied

Reason for Service Call: 6 Month Service Maintenance

Owner: Ed & Angela Williams Angelawilliams28@aol.com

Location: 1946 Ford Rd., Delaware County

Unscheduled Visit

Travel Time @ \$30/hr

Work Time @ \$60/hr

Depart Time: _____

Start Time: _____

Arrival Time: _____

End Time: _____

Scheduled Visit @ \$250

Aeration Unit

Yes No

Tank Inlet pipe clear Yes No

Tank riser's watertight Yes No

Scum layer developed Yes No

Tank needs pumped Yes No

Effluent clear Yes No

Effluent odor Yes No

Check & clean motor Yes No

Est. thickness: 1"

NOTES:

Pump Station

Tank riser's watertight Yes No

SDI filter replaced Yes No

Pump vault filter cleaned Yes No

Floats working properly Yes No

Dosing pump working Yes No

Control settings correct Yes No

Alarm working properly Yes No

Notes: _____

Notes: _____

Notes: _____

Notes: _____

Notes: _____

Notes: _____

Notes: _____

Current operations

Previous operations

12/17/2018

Pump 1 Run Time: (min.) 77,496

Pump 1 starts: 4,447

Design flow rate: 480

High Alarm counts: 50

Secondary counts: 69

Power Failures 118

Average daily flow : 43

Pump 1 Run Time: (min.) 74,940

Pump 1 starts: 4,300

Design flow rate: 480

High Alarm counts: 50

Secondary counts: 69

Power Failures 117

Average daily flow : 49

NOTES:

AH (

Absorption Field

Type:

Trenched

On Grade

On Sand

Field damaged:

Yes

No

Notes:

Airvent/boxes damaged

Yes

No

Notes:

System flush checked

Yes

No

Notes:

Vortex flush checked

Yes

No

Notes:

NOTES:

Pressure Readings

Not enough fluids to obtain pressure readings

Zone 1 (L)

Dosing in box

Flush in box

Dosing in field

Flush in field

Zone 2 (R)

Dosing in box

Flush in box

Dosing in field

Flush in field

Scat Unit

Yes

No

NOTES:

If your tanks have not been pumped in the last 4 years, please arrange to have them pumped. Pumping can be obtained by calling Marcus at 740-833-5166, The Pumper or Chas at 614-206-4627.

Important Notice: This service report indicates the present condition of the system based on observation by a trained technician. This does NOT cover any unobservable conditions, and is in no way a guarantee of warranty of past or future performance.